

STH 93 SB BRIDGE – B-18-0034 – March 25, 2019 - Temp = 43 degrees



SOUTH DECK JOINT



NORTH DECK JOINT



SOUTH ABUTMENT



SOUTH ABUTMENT





NORTH ABUTMENT BACKWALL



NORTH ABUTMENT



NORTH ABUTMENT



NORTHWEST ABUTMENT CORNER





PIER 1 GIRDER SPALL



PIER 1 DETERIORATION