

Bridge B-40-376 South Side (Looking North) on 124th Street



Bridge B-40-376 South Side (Looking North) on 124th Street




Bridge B-40-376 North Side (Looking South) on 124th Street




Bridge B-40-376 Looking West



Bridge B-40-376 Deck Cracks




Bridge B-40-376 Deck Cracks



Bridge B-40-376 Deck Cracks




Bridge B-40-376 Sidewalk Cracks



Bridge B-40-376 Sidewalk Cracks



Bridge B-40-376 Bridge/Approach Parapet Joint (SE Corner)



Bridge B-40-376 SE Corner Approach Sidewalk



Bridge B-40-376 North Approach Joint



Bridge B-40-376 NE Corner Wing Tip and Sidewalk




Bridge B-40-376 NE Corner Wing Tip and Sidewalk



Bridge B-40-376 NE Corner Approach & Drainage



Bridge B-40-376 NE Corner Approach



Bridge B-40-376 Gabion Wall at NE Corner



Bridge B-40-376 Gabion Wall at NE Corner




Bridge B-40-376 Gabion Wall at NE Corner




Bridge B-40-376 Gabion Wall at SE Corner



Bridge B-40-376 SW Corner Parapet Scaling & Cracking



Bridge B-40-376 South Approach Joint



Bridge B-40-376 Bridge/Approach Parapet Joint (SW Corner)



Bridge B-40-376 SW Corner (Looking NW)