

PHOTOGRAPHS OF EXISTING STRUCTURE B-58-60

Figure 1: Panoramic from bridge deck looking downstream and West	1
Figure 2: Panoramic from bridge deck looking upstream and East.....	1
Figure 3: Center of bridge deck looking South down STH 47	1
Figure 4: Center of bridge deck looking North down STH 47	2
Figure 5: Center of STH 47 looking North at bridge.....	2
Figure 6: Center of STH 47 looking South at bridge.....	3
Figure 7: West side of sidewalk looking South	3
Figure 8: West side of railing looking South	4
Figure 9: North end of bridge deck looking East.....	4
Figure 10: Center of bridge structure crack line looking East.....	5
Figure 11: South end of bridge deck looking East.....	5
Figure 12: West sidewalk looking North	6
Figure 13: West side of railing looking North	6
Figure 14: West side of railing looking East	7
Figure 15: South end of abutment looking East	7
Figure 16: Pier looking Northeast	8
Figure 17: Pier looking North	8
Figure 18: Southeast end of abutment	9
Figure 19: South end of abutment looking West.....	9
Figure 20: Northeast corner of bridge rip rap.....	10
Figure 21: Northwest corner of bridge rip rap.....	10
Figure 22: Southeast middle of guardrail looking North	11
Figure 23: East side of railing looking North	11
Figure 24: Southeast end of guardrail	12
Figure 25: Bridge structure name plate B-58-60 looking East	12
Figure 26: South end of bridge deck looking West.....	13
Figure 27: North end of bridge deck looking West.....	13
Figure 28: East side of sidewalk looking South	14
Figure 29: Northwest abutment/railing looking Southeast.....	14
Figure 30: North abutment looking East.....	15
Figure 31: Pier looking Southeast	15
Figure 32: North abutment looking west.....	16
Figure 33: Northeast corner of abutment	16
Figure 34: Northeast corner of abutment	17
Figure 35: Northwest corner of abutment/railing.....	17



Figure 1: Panoramic from bridge deck looking downstream and West



Figure 2: Panoramic from bridge deck looking upstream and East



Figure 3: Center of bridge deck looking South down STH 47



Figure 4: Center of bridge deck looking North down STH 47



Figure 5: Center of STH 47 looking North at bridge



Figure 6: Center of STH 47 looking South at bridge



Figure 7: West side of sidewalk looking South



Figure 8: West side of railing looking South



Figure 9: North end of bridge deck looking East



Figure 10: Center of bridge structure crack line looking East



Figure 11: South end of bridge deck looking East



Figure 12: West sidewalk looking North



Figure 13: West side of railing looking North



Figure 14: West side of railing looking East



Figure 15: South end of abutment looking East



Figure 16: Pier looking Northeast



Figure 17: Pier looking North



Figure 18: Southeast end of abutment



Figure 19: South end of abutment looking West



Figure 20: Northeast corner of bridge rip rap



Figure 21: Northwest corner of bridge rip rap



Figure 22: Southeast middle of guardrail looking North



Figure 23: East side of railing looking North



Figure 24: Southeast end of guardrail



Figure 25: Bridge structure name plate B-58-60 looking East



Figure 26: South end of bridge deck looking West



Figure 27: North end of bridge deck looking West



Figure 28: East side of sidewalk looking South



Figure 29: Northwest abutment/railing looking Southeast



Figure 30: North abutment looking East



Figure 31: Pier looking Southeast



Figure 32: North abutment looking west



Figure 33: Northeast corner of abutment



Figure 34: Northeast corner of abutment



Figure 35: Northwest corner of abutment/railing