



Wing 3 - RT of Centerline
Facing East

Wingwall to
be replaced



Wing 3 - RT of Centerline
Facing East



Wing 3 - RT of Centerline
Facing East

Wingwall to
be replaced



Wing 3 - RT of Centerline
Facing Southeast



Wing 3 - RT of Centerline
Facing Southeast



Wing 3 - RT of Centerline
Facing Southeast



Wing 3 - Inside Box Culvert
Facing South



Wing 3 - Inside Box Culvert
Facing South

Concrete
Surface Repair

Wingwall to
be replaced



Inside Box Culvert
Facing South



Inside Box Culvert
Facing South

Concrete
Surface Repair



Wing 3 - Inside Box Culvert
Facing South



Inside Box Culvert
Facing South

Exposed
Rebar



Cracking in Wing 3



Wing 3 - RT of Centerline
Facing Southwest

Wingwall to
be replaced



Wing 3 - RT of Centerline
Facing Southwest



Wingwall to
be replaced

Wing 3 - Embankment at Proposed Wingwall Replacement



Wing 3 - Embankment at Proposed Wingwall Replacement



Base of Wing 3



Base of Wing 3 - West End



Wing 3 - West End



24" CMCP in Wing 3