

**WisDOT Project ID 1090-35-00 / 1090-35-70**  
**Existing Bridge B-67-112– IH 43 NB over Martin Rd**  
Photos of Existing Conditions



South elevation, looking north. Photo from WisDOT inspection report.



Overview of top of deck, looking east. Taken from Google Earth.

**WisDOT Project ID 1090-35-00 / 1090-35-70**  
**Existing Bridge B-67-112– IH 43 NB over Martin Rd**  
**Photos of Existing Conditions**



East Abutment & Slope. Photo from WisDOT inspection report.



North Rail, Spalls. Photo from WisDOT inspection report.



**WisDOT Project ID 1090-35-00 / 1090-35-70**  
**Existing Bridge B-67-112– IH 43 NB over Martin Rd**  
Photos of Existing Conditions



West approach, Looking south and east side of deck. Photo from WisDOT inspection report.



West header, looking north. Photo from WisDOT inspection report.

**WisDOT Project ID 1090-35-00 / 1090-35-70**  
**Existing Bridge B-67-112– IH 43 NB over Martin Rd**  
**Photos of Existing Conditions**



Wearing surface at east header, looking south. Diagonal Cracks. Photo from WisDOT inspection report.