

Photographs of Bridge Components Requiring Repair

Project I.D. 7070-06-31

Cadott - Cornell

Big Drywood Creek Bridge B-09-0127

STH 27

Chippewa County

B-09-0127



Presstressed Girder

Remove and replace east exterior girder.





Concrete Deck

Remove and replace reinforced concrete deck.