

ATTACHMENT C
PHOTOS OF DEFICIENT AREAS

1050-01-11
Chippewa Falls – Abbotsford
Stillson Creek to Cardinal Ave
STH 29
Chippewa and Clark Counties
Structure Photos

B-09-171



Top of Deck – Delamination and Cracking



Underside of Deck – Diagonal Cracks with Efflorescence



Underside of Deck – Transverse Cracks with Efflorescence