

ATTACHMENT C
PHOTOS OF DEFICIENT AREAS

1050-01-11
Chippewa Falls – Abbotsford
Stillson Creek to Cardinal Ave
STH 29
Chippewa and Clark Counties
Structure Photos

B-09-174



Top of Deck



SW end of deck – Spalling and patch on edge



Underside of west span - Cracking



Underside of east span - Cracking



Underside of center span - Cracking