

ATTACHMENT C
PHOTOS OF DEFICIENT AREAS

1050-01-12
Chippewa Falls – Cadott
CTH X Bridge B-9-19
STH 29
Chippewa County
Structure Photos

B-9-19



Top of deck and expansion joint over pier 1



West edge of deck - spalling



Girder 1 – pin and hanger corrosion



Span 1 – Bottom flange of girder 4



Girder 2 at pier 1