

ATTACHMENT C
PHOTOS OF DEFICIENT AREAS

1050-01-11
Chippewa Falls – Abbotsford
Stillson Creek to Cardinal Ave
STH 29
Chippewa and Clark Counties
Structure Photos

B-09-20





East End of Deck



Top of deck



Underside of deck showing cracks with efflorescence.

