Design Quality Index Report 10/15/2019

Contract ID	2019	0312008				
Project ID	5516-00-70		County Monroe		Federal ID	wisc 2019153
Region			Number of Factors Rated	16	Highway	CTH W W
Total Factor Score	108		Construction on time?	Yes	Project Index	6.8
Evaluation Date	09/23	3/19	Consultant Design Firm		Project Cost	
Inhouse Design					Representing	
Raters	Elizal	beth Reis			Other	
<u>Remarks</u>			2 = Major to 3 = Moderate 4 = Moderate 5 = Minor co 6 = Minor to	blems, not constructab moderate construction p problems, constructab to minor construction p nstruction problems, no no construction problem	le without major plan or des problems, moderate design le, minor design or plan cha problems, minor to no desig plan or design changes ns	or plan changes inges
Factor	Rate	Comments		ruction problems		
Right of Way(adequate to construct)						
Horizontal Alignment(fit)	7.0					
Vertical Alignment (fit and drainage)	7.0					
Earthwork	7.0					
Work Zone Traffic Control Plans	7.0					
Erosion Control Plans	4.0		not allow for silt fence to be uti ely protect the waterway	lized for protection alon	g the south abutment and te	emporary shoring ended up be
Construction Staging	7.0					
Utility Coordination	7.0					
Special Provisions	7.0					
Consistency between plans and special provisions	7.0					
Drainage	7.0					
Quantities	7.0					
Contract Time	7.0					
Structures AVG.	6					
Plans accurate and complete	6.0					

Design Quality Index Report 10/15/2019

Soils information and Foundation Details	3.0	Additional pre-boring required due to bedrock elevation being higher than indicated in the plans; additional mobilization was required to complete pre-boring on north abutment after piling did not drive to required 10' embedment
Utility information accurate && complete	7.0	
Special Provisions clear and concise	7.0	
Ease of assembly and construction	7.0	
Survey	7.0	
Soils	7.0	