## Design Quality Index Report 9/26/2019

Contract ID	2018	1113007				
Project ID	5056	-00-70	Count	y Richland		Federal ID N/A
Region	SW		Number of Fac	tors Rated	16	Highway LOC STR Town
Total Factor Score	106.8	3	Constructior	n on time?	Yes	Project Index 6.7
Evaluation Date	09/26	6/19	Consultant De	esign Firm	Jewell	Project Cost 247,864.47
Inhouse Design						Representing
Raters	Brad	Schroeder				WisDOT
<u>Remarks</u>			2 3 2 5 6	2 = Major to n 3 = Moderate 4 = Moderate 5 = Minor con 6 = Minor to n	blems, not constructal noderate construction problems, constructal to minor construction	ple without major plan or design changes problems, moderate design or plan changes ple, minor design or plan changes problems, minor to no design or plan changes plan or design changes ns
Factor	<u>Rate</u>	<u>Comments</u>			,	
Right of Way(adequate to construct)	7.0					
Horizontal Alignment(fit)	7.0					
Vertical Alignment (fit and drainage)	7.0					
Earthwork	6.0	Had to change gra	iding in NE Quad to	o adjust to la	rge amounts of draina	ge after rains.
Work Zone Traffic Control Plans	7.0					
Erosion Control Plans	7.0					
Construction Staging	7.0					
Utility Coordination	7.0					
Special Provisions	7.0					
Consistency between plans and special provisions	7.0					
Drainage	6.0	Stream realignmer	nt had to be adjuste	ed.		
Quantities	6.0					
Contract Time	7.0					
Structures AVG.	6.8					
Plans accurate and complete	7.0					

## Design Quality Index Report 9/26/2019

Soils information and Foundation Details	6.0	Piling lengths were deeper than plan.
Utility information accurate && complete	7.0	
Special Provisions clear and concise	7.0	
Ease of assembly and construction	7.0	
Survey	6.0	
Soils	6.0	